

## Message Text

UNCLASSIFIED POSS DUPE

PAGE 01 BUENOS 00377 161558Z

70

ACTION OC-06

INFO OCT-01 ARA-10 ISO-00 CCO-00 FBIE-00 SS-20 /037 W

----- 117169

R 161335Z JAN 74

FM AMEMBASSY BUENOS AIRES

TO SECSTATE WASHDC 4986

UNCLAS BUENOS AIRES 0377

DEPT FOR ARA/RCO.

E.O. 11652: N/A

TAGS: ACOM.

SUBJECT: INOPERATIVE TELEPHONES IN LEGATT OFFICES.

THE INTERCOM LIGHTS DO NOT LIGHT UP IN THE LEGATT OFFICES  
WHEN THERE IS A INCOMING CALL OR WHEN A LINE IS IN USE.  
ALSO, ON INCOMING CALLS THE TELEPHONE HAS ONE CONTINUOUS  
RING. TRIED SWITCHING CORD BOARDS TO NO AVAIL. ANY  
INFORMATION TO SOLVE THIS PROBLEM WILL BE APPRECIATED.  
LOCAL TELEPHONE TECHNICIAN SAID THAT "THE SIGNAL MOTOR  
IN THE INTERCOMMUNICATION EQUIPMENT IS NOT FUNCTIONING"  
AND HE IS UNABLE TO REPAIR.  
KREBS

UNCLASSIFIED

NNN

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 JAN 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 16 JAN 1974  
**Decaption Date:** 01 JAN 1960  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Authority:** n/a  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01 JAN 1960  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1974BUENOS00377  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** n/a  
**Enclosure:** n/a  
**Executive Order:** N/A  
**Errors:** N/A  
**Film Number:** n/a  
**From:** BUENOS AIRES  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1974/newtext/t19740139/aaaabkha.tel  
**Line Count:** 39  
**Locator:** TEXT ON-LINE  
**Office:** ACTION OC  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:**  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** n/a  
**Review Action:** RELEASED, APPROVED  
**Review Authority:** elyme  
**Review Comment:** n/a  
**Review Content Flags:**  
**Review Date:** 14 MAY 2002  
**Review Event:**  
**Review Exemptions:** n/a  
**Review History:** RELEASED <14 MAY 2002 by daviscw>; APPROVED <20-Nov-2002 by elyme>  
**Review Markings:**

Declassified/Released  
US Department of State  
EO Systematic Review  
30 JUN 2005

**Review Media Identifier:**  
**Review Referrals:** n/a  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** INOPERATIVE TELEPHONES IN LEGATT OFFICES. THE INTERCOM LIGHTS DO NOT LIGHT UP IN THE LEGATT OFFICES  
**TAGS:** ACOM, AR  
**To:** STATE  
**Type:** TE  
**Markings:** Declassified/Released US Department of State EO Systematic Review 30 JUN 2005